RECEIVED 3. Number of Vehicles Involved: 435 100 JUL 26 P 12:51 Number of Vehicles Inspected and Repaired; 168 Number Inspected and Not Needing Repair: 0 Number of Vehicles Determined Unreachable for Inspection: Recall Subject: 03V-228 Vegas Fuel Tank Vent Obstruction (California) C. Report Quarter: 4th Quarter NHTSA Assigned Campaign Number: Q3V-228 Company Assigned Number: Bulletin V-03-03(A) Date Notification Began: <u>July 25, 2003</u> Date Notification was Completed: August 1, 2003 Number of Vehicles Involved: 122 CA models Number of Vehicles Inspected and Repaired: 55 Number Inspected and Not Needing Repair: 0 Number of Vehicles Determined Unreachable for Inspection: 0 Recall Subject: 03V-229 Vegas Fuel Tank Vent Obstruction (49St, CDN, UK) Ð. Report Quarter: 4th Ouarter NHTSA Assigned Campaign Number: 03V-229 Company Assigned Number: Bulletin V-03-04(A) Date Notification Began: <u>July 25, 2003</u> Date Notification was Completed: August 1, 2003 Number of Vehicles Involved: 1070 Number of Vehicles Inspected and Repaired; <u>318</u> Number Inspected and Not Needing Repair: Number of Vehicles Determined Unreachable for Inspection: Е. Recall Subject: 03V-336 Unexpected Sidestand Deployment Report Quarter: 3rd Quarter NHTSA Assigned Campaign Number: 03V-336 Company Assigned Number: Bulletin V-03-05SAF 2. Date Notification Began: November 6, 2003 Date Notification was Completed: November 13, 2003

9,120

Number of Vehicles Involved: